Approved For Release 2000/09/04 SIA-RDP8 1300878 R001400030121-5

GK SAPC-22871 Copy / of 7

DKDK

FreA-10)

MEMORANDUM FOR: Project Director

DEC 30 1957

25X1A

25X1A

ATTENTION

:

SUBJECT

"F" Rack

1. During the visit here of the two Ramo-Wooldridge engineers, the "F" Rack readout equipment was examined in detail. The equipment furnished to Headquarters suffered from two basic faults:

- a. At high input noise levels it is not possible to zero the DC amplifiers which drive the readout pen motors.
- b. "Cross talk" between the 10 second and 1 minute timing mark amplifiers does not allow suitable presentation of these two signals on the readout chart.
- c. Lack of any reference marks on the amplifier gain controls complicates using the rack and adds greatly to setup time.
- 2. The substance of these conclusions, which make it impossible to use the "F" Rack in its present form, have been relayed to R-W verbally both by the undersigned and by engineer who examined the equipment.
- 3. The "F" Rack should not be accepted for project use until these faults have been cleared up.



Distribution:

Copy 1 & 2 - fwd

25X1A

3 **-**4 **-**

5 & 6 - ESO

7 - Project Chron

Contract Fil

Approved For Release 2000/09/01 : CIA-RDP81B00878R001400030121-5

Approved For Release 2000/09/01 : CIA-RDP81B00878R001400030121-5

	SEMUER WILL CHI	ECK (	CLASSIFICON	TOP	AND BO	TTOM
	UNCLASSIFIED		CONFIDEN			SECRET
•	• • • • • • • • • • • • • • • • • • • •		NTELLIGENCE ACL			
то	NAME AN	D AD	DRESS	INI	TIALS	DATE
1			Acting ESO	A	1	26/2
2					' i	
3						
4						
5						
6		<b></b>				
	ACTION		DIRECT REPLY		PREPARE	
	APPROVAL	ļ	DISPATCH	X	<del></del>	ENDATION
Х,	COMMENT	-	FILE		<del></del>	
	CONCURRENCE	7	INFORMATION		SIGNATU	KE
ĺ						
	Jan - j	n l	on this mod, This	be	elica t sm looks done	ery pheils s OK.
	FOLD I	HERE	TO RETURN TO	SEN	<i>*</i>	DATE
	FOLD I	HERE ADDR	TO RETURN TO	SEN IO.	DER	